



# TATA PROJECTS LIMITED


Quality Services Division  
 2nd Floor ; Varun Towers - 1; Begumpet,  
 Hyderabad - 500 016  
 EPABX: 91 40 67258800 Fax: +91-40-66318806

<b>PURCHASE ORDER No.</b>
TPL/SBU/QS/NPCIL/PCT/075
Dated 10.05.2016

<b>Name of the Supplier/ Vendor</b>	<b>Your reference / Our reference</b>	<b>Quotation dated</b> 07.03.2016
Pishon Concrete Test (P) Ltd, No.653, Brindavan Avenue T.H.Road, Tondiarpet Chennai - 81 Attn: Mr.R.Ravi Prakash, Director	Sub : Visual Inspection, Rebound Hammer Test, Half Cell Potential Test, and Ultrasonic Pulse Testing and Chemical analysis of RCC columns at our Project site.  Ref : Your Quotation Ref.PCTPL/NDT/TPL/15-16/79, dated 07.03.2016	
Phone: 044-25912684		
Mobile 9444038181/ 8282		

Dear Sir,  
 With reference to the above offer and subsequent discussions, we are pleased to issue this PO for Inspection and NDT services.

### SCHEDULE OF PRICES & QUANTITY

S.No.	DESCRIPTION	UOM	Lump sum price for 7 Nos. (INR)
01	Visual Inspection, Rebound Hammer Test, Half Cell Potential Test, and Ultrasonic Pulse Testing and Chemical analysis of TG columns at Nagapattinam Project site as per Annexure-I.	7	

Total Contract Price : Rs. XXXXXXXXXX

#### 1. Price Basis :

The unit rate indicated above shall remain firm and fixed till the work is completed and shall not be subjected to any escalation on any account whatsoever may be.

#### 2. Payment Terms :

100% payment shall be made within 30 days after submission of inspection report. Applicable taxes will be extra.

#### 3. INSURANCE : Not applicable

4. Validity : Validity of this PO upto 31.05.2016

5. Delivery Schedule : Work to be commenced on 18th May 2016 or as indicated by TPL.

6.0 Deliverables: As per attached Annexure-I.

7.0 Special Instructions for Submission of Invoices for Payment :

7.1 Payment Through bank (RTGS). Please provide your Bank details.

7.2 You shall submit the following documents along with your invoices for payments .

a) Invoice showing Our PO number, description of work completed, quantity, lumps sum amount.

8.0 Insurance : not applicable

8.1 Risk Purchase : Not Applicable.

9.0 Business Ethics:

9.1 TPL required that the suppliers observe highest standard of ethics during the supply and execution of Order with TPL. You are requested to visit our web site [www.tataproyects.com](http://www.tataproyects.com) for viewing the full text of TATA Code of Conduct.

10.0 Safety: All safety of personnel working in this assignment shall be taken care by you and all the safety norms at project sites shall be strictly followed.

11.0 Order Acceptance:


11.1 This order is being issued to you in "Triplicate". Please return two acceptance copies of this order to Mr.P.P.Sastry, Asst.Vice President (QS) duly signed with your company seal as a token of your acceptance.

12.0 Post Order Correspondence after Returning Acceptance Copies :

12.1 Please quote above Purchase Order no. in all your future correspondence.

12.1 All your invoices for payment shall be forwarded to Mr.P.P.Sastry, Asst.Vice President (QS). While forwarding the invoices, please ensure that all supporting documents required for processing of invoices.

Yours truly yours

  
 P.P.SASTRY

Asst.Vice President (QS)



  
 SOURAV CHAKRABORTY

(Head-Finance & Accounts)

Refer TPL WO Ref.TPL/SBU/QS/NPPL/PCT/075, dated 09.05.2016.

Annexure-I

#### 1.0 Scope of Work

Following are the scope work and tests to be conducted in seven Number TG Column structures for assessment of concrete integrity, corrosion and surface hardness strength

- a. Detailed physical observation and inspection of any distress in the Seven Numbers TG Building Columns structure.
- b. Carrying out Rebound hammer test
- c. Carrying out Half-cell potential test
- d. Carrying out Ultrasonic pulse velocity testing
- e. Carrying out Chemical analysis

#### 2.0 Deliverables

Furnishing detailed test report in triplicate along with sketches, specifications, Photographs, conclusions and Recommendations etc shall be completed and submitted to us within four days from the date completion of inspection at Site.

The following are the contents in the report.

- i) Introduction / Salient features,
- ii) Physical observations / Photographs, deviations
- iii) Test data and consolidation of test data
- iv) Contouring report Analysis
- v) Conclusion and Recommendations.

#### 4.0 Work completion

The site inspection and testing as per S.No. 1 shall be completed in two days from the date of reporting of your team at Nagapattinam Site. The facilities required at site as per your offer ref.PCTPL/NDT/TPL/15-16/079 dt.07.03.16 will be provided.